



You need to add the following Parts to the manual ECUs*
to make the additional PWM Output (Low Side Driver) on Pin B24 work:

TIP122 (NPN Power Transistor)

1kOhm Resistor

1N4001 Diode



* (on automatic ECUs there is already a High Side Driver installed)